PER-2 DS

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score 153

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *PER-3*	LOCATION: *Ass#6*
STATION: DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-05-44.9* LONG: *82-38-22.1*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-11-09* TIME: _:_ ☐ AM ☑PM	INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☑ Intermittent showers
☑	☐ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *64* °F. Inches rainfall in past 24 hours ___ in

100 % Cloud Cover

P-Chem: Temp (°F) *45.4* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *210* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*6*	ft
Stream Width BF	*8*	ft
Range of Depth	*0.2-1.0*	ft
Bankfull Depth	*1*	ft
Est. Reach Length		ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☑ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☑ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☐ Normal
☑ High ☐ Very Rapid or Torrential

Stream Type;
☑ Perennial ☐ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☑ Trees ☐ Shrubs
☐ Grasses ☐ Herbaceous
Number of Strata *1*

Dom. Tree/Shrub Taxa
Poplar
Oak
(a few)

Canopy Cover;
☑ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *60* %	Run; ___ %	Pool *40* %
Silt/Clay (<0.06 mm)	*10*		*30*
Sand (0.06-2 mm)	*10*		*30*
Gravel (2-64 mm)	*60*		*30*
Cobble (64-256 mm)	*15*		*5*
Boulders (>256 mm)	*5*		*5*
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

PER-3

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score 80

NOTES/COMMENTS; Deep pools at culverts, channelized along road.

High Gradient Stream Data Sheet

STREAM NAME: *INT-1*	LOCATION: *Ass#25*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-04-10.1* LONG: *82-40-12.0*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-24-09* TIME: ___ ☐ AM ☑PM	INVESTIGATORS; *Rob Lewis, Julie Clark*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☐ Intermittent showers
☑	☑ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *40* °F. Inches rainfall in past 24 hours ___ in

0 % Cloud Cover

P-Chem: Temp (°F) *43.6* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *122* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*0.7*	ft
Stream Width BF	*1.5*	ft
Range of Depth	*0.1-0.75*	ft
Bankfull Depth	*1.0*	ft
Est. Reach Length	___	ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☐ Forest
☐ Deep Mining	☐ Commercial	☑ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☐ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☑ Normal
☐ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation: Dom. Tree/Shrub Taxa
Dominate Type:
☐ Trees ☐ Shrubs
☑ Grasses ☑ Herbaceous
Number of Strata *2*

Canopy Cover;
☑ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *40* %	Run; *20* %	Pool *40* %
Silt/Clay (<0.06 mm)	*20*	*20*	*40*
Sand (0.06-2 mm)	*20*	*20*	*40*
Gravel (2-64 mm)	*60*	*60*	*20*
Cobble (64-256 mm)		*(debris jams)*	
Boulders (>256 mm)			
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-1

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-2*	LOCATION: *Ass#28*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-04-12.9* LONG: *82-39-52.1*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-25-09* TIME: _:_ ☑ AM ☐PM	INVESTIGATORS; *Rob Lewis, Julie Clark*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☐ Intermittent showers
☑	☑ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *37* °F. Inches rainfall in past 24 hours ___ in

30 % Cloud Cover

P-Chem: Temp (°F) *34.4* D.O. (mg/l) ____ % Saturation ____ pH(S.U.) ____ Cond.µs *186* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*4*	ft
Stream Width BF	*6*	ft
Range of Depth	*0.1-0.5*	ft
Bankfull Depth	*0.8*	ft
Est. Reach Length		ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☐ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☑ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☐ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☑ Normal
☐ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☑ Trees ☐ Shrubs
☐ Grasses ☐ Herbaceous
Number of Strata *1*

Dom. Tree/Shrub Taxa
Black walnut
Sycamore
Sugar maple

Canopy Cover;
☐ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☑ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *70* %	Run; *10* %	Pool *20* %
Silt/Clay (<0.06 mm)			
Sand (0.06-2 mm)	*30*	*30*	*30*
Gravel (2-64 mm)	*30*	*30*	*30*
Cobble (64-256 mm)	*40*	*40*	*40*
Boulders (>256 mm)			
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale)	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-2

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-3*	LOCATION: *Ass#24*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-04-26.0* LONG: *82-39-44.9*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-12-09* TIME: _:_ ☐ AM ☑ PM	INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☑ Heavy rain
☐	☐ Steady rain
☐	☐ Intermittent showers
☑	☐ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑ Yes ☐ No

Air temperature *44* °F. Inches rainfall in past 24 hours ___ in

0 % Cloud Cover

P-Chem: Temp (°F) *45.5* D.O. (mg/l) ____ % Saturation ____ pH(S.U.) ____ Cond.µs *424* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*1*	ft
Stream Width BF	*1.5*	ft
Range of Depth	*0.1-0.4*	ft
Bankfull Depth	*0.5*	ft
Est. Reach Length		ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☐ Forest
☐ Deep Mining	☐ Commercial	☑ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☑ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☐ Normal
☑ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☐ Trees ☐ Shrubs
☑ Grasses ☐ Herbaceous
Number of Strata *1*

Dom. Tree/Shrub Taxa

Canopy Cover;
☑ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *80* %	Run; ____ %	Pool *20* %
Silt/Clay (<0.06 mm)	*25*		*40*
Sand (0.06-2 mm)	*40*		*25*
Gravel (2-64 mm)	*30*		*35*
Cobble (64-256 mm)	*5*		
Boulders (>256 mm)			
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-3

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-4*	LOCATION: *Ass#33*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-04-39.8* LONG: *82-39-29.9*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-25-09* TIME: __:__ ☐ AM ☑PM	INVESTIGATORS; *Rob Lewis, Julie Clark*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☐ Intermittent showers
☑	☑ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *52* °F. Inches rainfall in past 24 hours ___ in

0 % Cloud Cover

P-Chem: Temp (°F) *45* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *148.5* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*2*	ft
Stream Width BF	*5*	ft
Range of Depth	*0-0.75*	ft
Bankfull Depth	*0.5*	ft
Est. Reach Length	___	ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☐ Forest
☐ Deep Mining	☐ Commercial	☑ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☑ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☑ Normal
☐ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☐ Trees ☐ Shrubs
☐ Grasses ☑ Herbaceous
Number of Strata *1*

Dom. Tree/Shrub Taxa
Box elder

Canopy Cover;
☑ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☐ Channelization
(☐ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *1* %	Run; *50* %	Pool *50* %
Silt/Clay (<0.06 mm)		*100*	*100*
Sand (0.06-2 mm)		*(detritus/vegetation)*	
Gravel (2-64 mm)			
Cobble (64-256 mm)			
Boulders (>256 mm)			
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-4

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-5*	LOCATION: *Ass#23*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-04-52.2* LONG: *82-39-21.7*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-12-09* TIME: _:_ ☐ AM ☑ PM	INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☑ Heavy rain
☐	☐ Steady rain
☐	☐ Intermittent showers
☑	☐ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑ Yes ☐ No

Air temperature *42* °F. Inches rainfall in past 24 hours ___ in

0 % Cloud Cover

P-Chem: Temp (°F) *43.7* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *132* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*1.4*	ft
Stream Width BF	*2.0*	ft
Range of Depth	*0.1-0.3*	ft
Bankfull Depth	*0.4*	ft
Est. Reach Length		ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☑ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☐ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☐ Normal
☑ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☑ Trees ☑ Shrubs
☐ Grasses ☐ Herbaceous
Number of Strata *2*

Dom. Tree/Shrub Taxa
Cherry
Sycamore

Canopy Cover;
☐ Fully Exposed (0-25%)
☑ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☐ Full ☑ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *30* %	Run; *20* %	Pool *50* %
Silt/Clay (<0.06 mm)	*60*	*60*	*60*
Sand (0.06-2 mm)			
Gravel (2-64 mm)	*35*	*35*	*35*
Cobble (64-256 mm)	*5*	*5*	*5*
Boulders (>256 mm)			
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-5

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-6*	LOCATION: *Ass#29*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-05-03.1* LONG: *82-39-20.5*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-25-09* TIME: _:_ ☑ AM ☐PM	INVESTIGATORS; *Rob Lewis, Julie Clark*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☐ Intermittent showers
☑	☑ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *38* °F. Inches rainfall in past 24 hours ___ in

30 % Cloud Cover

P-Chem: Temp (°F) *37* D.O. (mg/l) ____ % Saturation ____ pH(S.U.) ____ Cond.µs *155.5* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*2*	ft
Stream Width BF	*3*	ft
Range of Depth	*0.1*	ft
Bankfull Depth	*0.4*	ft
Est. Reach Length	____	ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☐ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☐ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☑ Normal
☐ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☑ Trees ☑ Shrubs
☐ Grasses ☑ Herbaceous
Number of Strata *3*

Dom. Tree/Shrub Taxa
American hornbeam
Rubus species
Red maple

Canopy Cover;
☐ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☑ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *80* %	Run; ____ %	Pool *20* %
Silt/Clay (<0.06 mm)	*10*		*20*
Sand (0.06-2 mm)	*30*		*40*
Gravel (2-64 mm)	*50*		*40*
Cobble (64-256 mm)	*10*		
Boulders (>256 mm)			
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-6

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score 120

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-7 US*	LOCATION: *Ass#18*
STATION: DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-05-16.1* LONG: *82-39-05*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-11-09* TIME: _:_ ☐ AM ☑PM	INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☑	☑ Intermittent showers
☐	☐ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *60* °F. Inches rainfall in past 24 hours ___ in

100 % Cloud Cover

P-Chem: Temp (°F) *50.4* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *137* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*2*	ft
Stream Width BF	*3*	ft
Range of Depth	*0.1-0.5*	ft
Bankfull Depth	*0.75*	ft
Est. Reach Length		ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☐ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☑ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☑ Normal
☐ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation: Dom. Tree/Shrub Taxa
Dominate Type:
☐ Trees ☐ Shrubs
☑ Grasses ☑ Herbaceous
Number of Strata *2*

Canopy Cover;
☑ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *50* %	Run; ___ %	Pool *50* %
Silt/Clay (<0.06 mm)			
Sand (0.06-2 mm)	*40*		*60*
Gravel (2-64 mm)	*60*		*40*
Cobble (64-256 mm)			
Boulders (>256 mm)			
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-7 US

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-7 DS*	LOCATION: *Ass#19*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-05-09.6* LONG: *82-39-16.9*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-12-09* TIME: _:_ ☑ AM ☐ PM	INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☑ Heavy rain
☐	☐ Steady rain
☐	☐ Intermittent showers
☑	☐ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑ Yes ☐ No

Air temperature *34* °F. Inches rainfall in past 24 hours ___ in

30 % Cloud Cover

P-Chem: Temp (°F) *42.5* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *188* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*4.5*	ft
Stream Width BF	*10*	ft
Range of Depth	*0.1-1.5*	ft
Bankfull Depth	*1.25*	ft
Est. Reach Length		ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☐ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☐ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☐ Normal
☑ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☑ Trees ☐ Shrubs
☐ Grasses ☐ Herbaceous
Number of Strata *1*

Dom. Tree/Shrub Taxa
Hornbeam
Oak
Sycamore
Beech

Canopy Cover;
☐ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☑ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☐ Full ☑ Partial)
(Upstream altered)

Substrate ☑ Est. ☐ P.C	Riffle *40* %	Run; *20* %	Pool *40* %
Silt/Clay (<0.06 mm)	*10*	*10*	*20*
Sand (0.06-2 mm)	*20*	*20*	*40*
Gravel (2-64 mm)	*40*	*40*	*30*
Cobble (64-256 mm)	*30*	*25*	*10*
Boulders (>256 mm)			
Bedrock		*5*	

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-7 DS

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score 129

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-8*	LOCATION: *Ass#22*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-05-10* LONG: *82-39-13.2*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-12-09* TIME: _:_ ☑ AM ☐PM	INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☑ Heavy rain
☐	☐ Steady rain
☐	☐ Intermittent showers
☑	☐Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *40* °F. Inches rainfall in past 24 hours __ in

10 % Cloud Cover

P-Chem: Temp (°F) *44* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *73.4* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*3*	ft
Stream Width BF	*5*	ft
Range of Depth	*0.1-0.5*	ft
Bankfull Depth	*0.6*	ft
Est. Reach Length	___	ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☑ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☑ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☐ Normal
☑ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☑ Trees ☑ Shrubs
☐ Grasses ☐ Herbaceous
Number of Strata *2*

Dom. Tree/Shrub Taxa
Oak
Sycamore

Canopy Cover;
☐ Fully Exposed (0-25%)
☑ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☐ Full ☑ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *60* %	Run; ___ %	Pool *40* %
Silt/Clay (<0.06 mm)	*10*		*20*
Sand (0.06-2 mm)	*20*		*30*
Gravel (2-64 mm)	*40*		*40*
Cobble (64-256 mm)	*25*		*10*
Boulders (>256 mm)	*5*		
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-8

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score 120

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-9* | LOCATION: *Ass#30*

STATION: | DRAINAGE AREA (AC) | BASIN/WATERSHED *Big Sandy River*

LAT: *38-05-17.5* LONG: *82-39-05.3* | COUNTY; *Lawrence* USGS 7.5 TOPO;

DATE: *2-25-09* TIME: _:_ ☑ AM ☐PM | INVESTIGATORS; *Rob Lewis, Julie Clark*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☐ Intermittent showers
☑	☑ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *40* °F. Inches rainfall in past 24 hours ___ in

50 % Cloud Cover

P-Chem: Temp (°F) *40.3* D.O. (mg/l) ____ % Saturation ____ pH(S.U.) ____ Cond.µs *413* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*2.5*	ft
Stream Width BF	*4.0*	ft
Range of Depth	*0.1-0.3*	ft
Bankfull Depth	*0.4*	ft
Est. Reach Length		ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☐ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☑ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☑ Normal
☐ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☑ Trees ☑ Shrubs
☐ Grasses ☑ Herbaceous
Number of Strata ____

Dom. Tree/Shrub Taxa
Red oak
White oak
Beech

Canopy Cover;
☐ Fully Exposed (0-25%)
☑ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *20* %	Run; *30* %	Pool *50* %
Silt/Clay (<0.06 mm)	*40*	*40*	*40*
Sand (0.06-2 mm)	*20*	*20*	*40*
Gravel (2-64 mm)	*40*	*40*	*20*
Cobble (64-256 mm)			
Boulders (>256 mm)			
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-9

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score 83

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-10*	LOCATION: *Ass#17*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-05-36.6* LONG: *82-38-42.3*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-11-09* TIME: _:_ ☐ AM ☑PM	INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☑ Intermittent showers
☑	☐ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *70* °F. Inches rainfall in past 24 hours ___ in

80 % Cloud Cover

P-Chem: Temp (°F) *52.4* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *247* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*1*	ft
Stream Width BF	*2*	ft
Range of Depth	*0.1-0.4*	ft
Bankfull Depth	*0.5*	ft
Est. Reach Length		ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☑ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☑ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☐ Normal
☑ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☑ Trees ☑ Shrubs
☐ Grasses ☐ Herbaceous
Number of Strata *2*

Dom. Tree/Shrub Taxa
Dogwood
Willow
Oak

Canopy Cover;
☐ Fully Exposed (0-25%)
☑ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *60* %	Run; *20* %	Pool *20* %
Silt/Clay (<0.06 mm)	*10*	*10*	*10*
Sand (0.06-2 mm)	*10*	*10*	*10*
Gravel (2-64 mm)	*50*	*50*	*50*
Cobble (64-256 mm)	*30*	*30*	*30*
Boulders (>256 mm)	*(Class III channel lining)*		
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-10

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score 99

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-11 US*	LOCATION: *Ass#14*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-05-35* LONG: *82-38-34*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-11-09* TIME: __:__ ☐ AM ☑PM	INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☑ Intermittent showers
☑	☐ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *65* °F. Inches rainfall in past 24 hours ___ in

75 % Cloud Cover

P-Chem: Temp (°F) *49* D.O. (mg/l) ____ % Saturation ____ pH(S.U.) ____ Cond.µs *104* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*4.5*	ft
Stream Width BF	*6.5*	ft
Range of Depth	*0.1-1.0*	ft
Bankfull Depth	*0.75*	ft
Est. Reach Length	____	ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☑ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:

☐ Dams	☐ Bridge Abutments	
☐ Island	☐ Waterfalls	
☐ Other	☐ Culverts	

Stream Flow;

☐ Dry ☐ Pooled ☐ Low ☐ Normal
☑ High ☐ Very Rapid or Torrential

Stream Type;

☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:

Dominate Type:

☑ Trees ☑ Shrubs
☑ Grasses ☑ Herbaceous

Number of Strata *4*

Dom. Tree/Shrub Taxa

White oak
Sycamore
Red cedar

Canopy Cover;

☐ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☑ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;

☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)
(long ago for Ag.)

Substrate ☑ Est. ☐ P.C	Riffle *70* %	Run; ____ %	Pool *30* %
Silt/Clay (<0.06 mm)	*20*		*20*
Sand (0.06-2 mm)			
Gravel (2-64 mm)	*50*		*50*
Cobble (64-256 mm)	*25*		*25*
Boulders (>256 mm)	*5*		*5*
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT - 11 US

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	**20 19 18 17 16**	**15 14 13 12 11**	**10 9 8 7 6**	**5 4 3 2 1 0**
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**
SCORE (RB)	**Right Bank 10 9**	**8 7 6**	**5 4 3**	**2 1 0**

Total Score

NOTES/COMMENTS;

High Gradient Stream Data Sheet

STREAM NAME: *INT-11 DS* | LOCATION: *Ass#13*

STATION: | DRAINAGE AREA (AC) | BASIN/WATERSHED *Big Sandy River*

LAT: *38-05-38.3* LONG: *82-38-33.3* | COUNTY; *Lawrence* USGS 7.5 TOPO;

DATE: *2-11-09* TIME: __:__ ☐ AM ☑ PM | INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☑ Intermittent showers
☑	☐ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑ Yes ☐ No

Air temperature *65* °F. Inches rainfall in past 24 hours ___ in

75 % Cloud Cover

P-Chem: Temp (°F) *48.4* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *120* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*5*	ft
Stream Width BF	*8*	ft
Range of Depth	*0.1-1.5*	ft
Bankfull Depth	*1*	ft
Est. Reach Length	___	ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☐ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☑ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☐ Normal
☑ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation: Dom. Tree/Shrub Taxa
Dominate Type:
☐ Trees ☐ Shrubs
☑ Grasses ☑ Herbaceous
Number of Strata *2*

Canopy Cover;
☑ Fully Exposed (0-25%)
☐ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☑ Channelization
(☑ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle ___ %	Run; ___ %	Pool *100* %
Silt/Clay (<0.06 mm)			
Sand (0.06-2 mm)			*25*
Gravel (2-64 mm)			*25*
Cobble (64-256 mm)			*25*
Boulders (>256 mm)			*25*
Bedrock			

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

INT-11 DS

4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills > 75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr.) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40-80% of stream reach channelized and disrupted.	Banks shored with gabion of cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
7 Frequency of Riffles	Occurrence of riffles relatively frequent; spacing between riffles 5 to 7 stream widths. Variety of habitat is key. In streams where riffles are continuous, boulders or logs are important.	Occurrence of riffles infrequent; distance between riffles divided by stream width is between 7 to 15.	Occasional riffle or bend: bottom contours provide some habitat; distance between riffles divided by stream width is between 15 to 25.	Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by stream width is > than 25.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
8. Bank Stability	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable, infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable, 30-60% of bank in reach has areas of erosion, high erosion potential during floods.	Unstable, many eroded areas, "raw" areas frequently along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.
SCORE (LB)	**Left Bank** 10 9	8 7 6	5 4 3	2 1 0
SCORE (RB)	**Right Bank** 10 9	8 7 6	5 4 3	2 1 0
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.	50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation; disruptive of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.
SCORE (LB)	**Left Bank** 10 9	8 7 6	5 4 3	2 1 0
SCORE (RB)	**Right Bank** 10 9	8 7 6	5 4 3	2 1 0
10. Riparian Vegetative Zone Width (score each bank riparian zone).	Width of riparian zone > 18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.	Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.
SCORE (LB)	**Left Bank** 10 9	8 7 6	5 4 3	2 1 0
SCORE (RB)	**Right Bank** 10 9	8 7 6	5 4 3	2 1 0

Total Score

NOTES/COMMENTS; Assessment site is between existing culverts.

High Gradient Stream Data Sheet

STREAM NAME: *INT-12 US*	LOCATION: *Ass#10*
STATION: / DRAINAGE AREA (AC)	BASIN/WATERSHED *Big Sandy River*
LAT: *38-05-38* LONG: *82-38-19*	COUNTY; *Lawrence* USGS 7.5 TOPO;
DATE: *2-11-09* TIME: _:_ ☑ AM ☐PM	INVESTIGATORS; *Rob Lewis, Rick Heil*

TYPE SAMPLE: ☐ P-CHEM ☐ Macroinvertebrate ☐ FISH ☐ BACT.

WEATHER:

Now	Past 24 hours
☐	☐ Heavy rain
☐	☐ Steady rain
☐	☑ Intermittent showers
☑	☐ Clear/sunny

Has there been a heavy rain in the last 7 days? ☑Yes ☐No

Air temperature *60* °F. Inches rainfall in past 24 hours ___ in

60 % Cloud Cover

P-Chem: Temp (°F) *44* D.O. (mg/l) ___ % Saturation ___ pH(S.U.) ___ Cond.µs *111* ☐ Grab

INSTREAM WATERSHED FEATURES

Stream Width EOW	*3*	ft
Stream Width BF	*5*	ft
Range of Depth	*0.1-1.5*	ft
Bankfull Depth	*0.75*	ft
Est. Reach Length	___	ft

LOCAL WATERSHED FEATURES:

Predominant Surrounding Land Use:

☐ Surface Mining	☐ Construction	☑ Forest
☐ Deep Mining	☐ Commercial	☐ Pasture/Grazing
☐ Oil Wells	☐ Industrial	☐ Silviculture
☐ Land Disposal	☐ Row Crops	☐ Urban Runoff/Storm Sewers

Hydraulic Structures:
☐ Dams ☐ Bridge Abutments
☐ Island ☐ Waterfalls
☐ Other ☐ Culverts

Stream Flow;
☐ Dry ☐ Pooled ☐ Low ☐ Normal
☑ High ☐ Very Rapid or Torrential

Stream Type;
☐ Perennial ☑ Intermittent
☐ Ephemeral ☐ Seep

Riparian Vegetation:
Dominate Type:
☑ Trees ☐ Shrubs
☐ Grasses ☐ Herbaceous
Number of Strata *1*

Dom. Tree/Shrub Taxa
Dogwood
Oak
Poplar

Canopy Cover;
☐ Fully Exposed (0-25%)
☑ Partially Exposed (25-50%)
☐ Partially Shaded (50-75%)
☐ Fully Shaded (75-100%)

Channel Alterations;
☐ Dredging
☐ Channelization
(☐ Full ☐ Partial)

Substrate ☑ Est. ☐ P.C	Riffle *33* %	Run; *33* %	Pool *34* %
Silt/Clay (<0.06 mm)	*10*	*10*	*20*
Sand (0.06-2 mm)	*20*	*10*	*40*
Gravel (2-64 mm)	*60*	*10*	*30*
Cobble (64-256 mm)	*10*	*10*	*5*
Boulders (>256 mm)			*5*
Bedrock		*60*	

Habitat Parameter	Condition Category: Optimal	Suboptimal	Marginal	Poor
1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient.	40-70% mix of stable habitat; well suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of new fall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20-% stable habitat" lack of habitat is obvious; substrate unstable or lacking.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
2. Embeddedness	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow. Deep > 1.5 feet.	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes)	Only 2 of the 4 habitat regimes present (if fast-shallow or slow shallow are missing, score low)	Dominated by 1 velocity/depth regime.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0